

## Notices of Violation Issued August 2011

Nov #	Facility	Location	Source Of Violation	Violation Date	Rule
9782	NAPTH LLC / 1611 S. Blosser Rd	Santa Maria	Multiple vapor recovery defects and failed tests	8/1/2011	316
9688	SYV Union High School	Santa Ynez	Failure to perform annual boiler tune-up	8/2/2011	206
9709	Sierra Resources / H.P. Boyne Lease	Santa Maria	Failure to obtain permit for 13 engines	8/5/2011	201
9634	Superor Collision Repair	Santa Barbara	Failed to properly maintain spray booth	8/8/2011	206
9799	UCSB / B562	Santa Barabara	Installation and operation of two boilers w/out permits	8/12/2011	201
9710	Greka Oil & Gas Co. / Morganti Lease	Santa Maria	Venting uncontrolled gas to atmosphere	8/12/2011	325
9689	Hanson Aggregates / Goleta Plant	Goleta	Did not submit operating permit application	8/16/2011	206
9690	Art-Craft Paint, Inc.	Santa Maria	Failure to record and report coating use	8/18/2011	206
9657	Cingular / Santa Maria	Santa Maria	Failure to mainatin records and submit annual report	8/19/2011	206
9635	Schwan Brothers	Goleta	Multiple violations of the autobody regulation	8/25/2011	339

## Penalty Settlement Payments Received August 2011

Nov #	Facility	Location	Source Of Violation	Violation Date	Rule	Date Paid	Total Penalty Received
9609	Main Street Farms	Santa Maria	Failure to register engines	8/5/2010	1201	8/1/2011	1,000
9610	Baroda Farms	Lompoc	Failure to register engines	8/5/2010	1201	8/1/2011	1,000
9699	Breitburn Energy / Pinal Lease	Santa Maria	Operated a loading rack without vapor recovery	3/9/2011	346	8/2/2011	183,500
9429	Venoco / Barge Jovalan	State Tidelands	Exceeded VRU emission standard	2/4/2010	206	8/5/2011	2,500
9615	Kern Ridge Growers	Cuyama	Failure to register engines	10/21/2010	1201	8/8/2011	1,500
9744	E & B Nat. Resources / Gas Plant 10	Cuyama	Exceeded major valve leak thresholds	12/21/2010	331	8/22/2011	1,000
9752	ExxonMobil Production Co. / POPCO Gas Plant	Gaviota	Failure to maintain CEMS analyzer	2/16/2011	206	8/22/2011	2,750
9753	ExxonMobil Production Co. / POPCO Gas Plant	Gaviota	Pilot flame not maintained in thermal oxidizer	2/16/2011	359	8/22/2011	5,000
9754	ExxonMobil Production Co. / Las Flores Canyon	Gaviota	Failure to analyze flare gas samples.	2/16/2011	206	8/22/2011	1,500
9755	ExxonMobil Production Co. / Las Flores Canyon	Gaviota	Flared ammonia gas	2/16/2011	206	8/22/2011	250
9757	ExxonMobil Production Co. / Las Flores Canyon	Gaviota	Failure to comply with PERP Regulation	2/16/2011	PERP	8/22/2011	100
9758	ExxonMobil Production Co. / Platform Heritage	OCS	Exceeded number of allowable piping gas leaks	2/16/2011	331	8/22/2011	250
9620	Fortistar Methane Group / Tajiguas Landfill	Gaviota	Failure to perform required monitoring	10/25/2010	206	8/24/2011	1,000
					<b>Total</b>		<b>\$201,350</b>