

Notices of Violation Issued July 2015

Nov #	Facility	Location	Source Of Violation	Self Reported	Violation Issued	Rule
10687	Lompoc Oil and Gas Plant - Freeport-McMoRan	Lompoc	Exceeded ambient H2S limit on 3-minute average	x	7/13/2015	206
10688	Platform Harvest - Freeport-McMoRan	OCS	Exceeded SCR emissions limits	x	7/13/2015	206
10689	Las Flores Canyon - ExxonMobil Production Company	Goleta	Exceeded allowable 30 min. runtime for diesel engine	x	7/2/2015	206
10690	Platform Hermosa - Freeport-McMoRan	OCS	Exceeded the hours/year limit on equipment	x	7/13/2015	206
10691	Platform Irene - Freeport-McMoRan	OCS	Exceeded coating limit	x	7/13/2015	323
10692	Platform Hermosa - Freeport-McMoRan	OCS	Exceeded coating limit	x	7/13/2015	323
10693	Las Flores Canyon - ExxonMobil Production Company	Goleta	Operated WGI with wrong multiplier set	x	7/2/2015	206
10694	Platform Irene - Freeport-McMoRan	OCS	Exceeded the allowable leaks	x	7/13/2015	206
10695	Platform Heritage - ExxonMobil Production Company	OCS	Exceeded limit during performance test	x	7/2/2015	206
10696	Platform Harmony - ExxonMobil Production Company	OCS	Exceeded limit during performance test	x	7/2/2015	206
10697	La Purisima Lease - Freeport McMoRan	Lompoc	Uncontrolled venting	x	7/13/2015	206/325
10742	Crystal Cleaners	Santa Maria	Failed to maintain trained operator certification		7/6/2015	ATCM
10744	Main St, 1038 E. (MVFF) - Main Street Petroleum	Santa Maria	Failed to conduct biannual VRS testing		7/28/2015	206
10855	Goleta Valley Cottage Hospital	Goleta	Failed to adhere to SCDP requirements		7/30/2015	206
10856	Goleta Valley Cottage Hospital	Goleta	Failed to adhere to SCDP requirements		7/30/2015	206
10874	Lompoc Oil and Gas Plant - Freeport-McMoRan	Lompoc	Uncontrolled venting	x	7/13/2015	206
10875	Platform Harmony - ExxonMobil Production Company	OCS	Failed to obtain written authorization for PERP	x	7/2/2015	202
10876	Las Flores Canyon - ExxonMobil Production Company	Goleta	Released excess ROCs	x	7/2/2015	206
10877	Platform Hondo - ExxonMobil Production Company	OCS	Loss of propane fuel gas to flare pilots	x	7/2/2015	206/359
10878	Platform Hidalgo - Freeport McMoRan	OCS	Exceeded the allowable data loss	x	7/13/2015	206
10879	Platform Hermosa - Freeport-McMoRan	OCS	Exceeded the allowable data loss	x	7/13/2015	206
10880	Gaviota Oil Heating Facility - Freeport McMoRan	Gaviota	Exceeded the allowable data loss	x	7/13/2015	206
10881	Las Flores Canyon - ExxonMobil Production Company	Goleta	Failed to meet NOx and SCR limits at Cogen Plant	x	7/2/2015	206
10882	Las Flores Canyon - ExxonMobil Production Company	Goleta	Failed to meet NOx and SCR limits at Cogen Plant	x	7/2/2015	206
10883	Las Flores Canyon - ExxonMobil Production Company	Goleta	Exceeded CO limits at the Cogen Plant	x	7/2/2015	206
10884	POPCO - ExxonMobil Production Company	Goleta	Exceeded H2S planned flaring limit	x	7/2/2015	206
10885	Platform Harvest - Freeport-McMoRan	OCS	Exceeded the sulfur content limit	x	7/13/2015	206
10886	POPCO - ExxonMobil Production Company	Goleta	Exceeded NOx limit from boiler	x	7/2/2015	206
10887	Las Flores Canyon - ExxonMobil Production Company	Goleta	Exceeded the allowable CEMs downtime	x	7/2/2015	206
10888	Betteravia Rd., 1220 E. (MVFF)	Santa Maria	Failure to maintain equipment as certified by ARB & recordkeeping		7/24/2015	206/316
10925	Tognazzini - Adams Lease - Golden Gate Oil, LLC	Santa Maria	Operated equipment without District permit		7/28/2015	201
10926	SMV Minerals Lease - Golden Gate Oil, LLC	Santa Maria	Operated equipment without District permit		7/28/2015	201
10927	Avenue of the Flags, 631 (MVFF)	Buellton	Failed to maintain recordkeeping		7/14/2015	206

Penalty Settlement Payments Received July 2015

Nov #	Facility	Location	Source Of Violation	Violation Issued	Rule	Date Paid	Total Penalty Received
10788	State St, 3060 (MVFF) - Conico State, LLC	Santa Barbara	Conducted pre-testing on VRS equipment	4/8/2015	206	7/8/2015	\$500
10445	Milpas St, 8 S. (MVFF) - Tesoro Refining & Marketing	Santa Barbara	Failed to submit the 2014 Annual Report	4/10/2015	206	7/20/2015	\$250
10849	H St, 1000 N. (MVFF) - Tesoro Refining & Marketing	Santa Barbara	Failed to submit the 2014 Annual Report	4/10/2015	206	7/20/2015	\$500
10850	Carrillo St, 636 W. (MVFF) - Tesoro Refining & Marketing	Santa Barbara	Failed to submit the 2014 Annual Report	4/10/2015	206	7/20/2015	\$250
10851	Carrillo St, 340 W. (MVFF) - Tesoro Refining & Marketing	Santa Barbara	Failed to submit the 2014 Annual Report	4/10/2015	206	7/20/2015	\$250
10852	Broadway, 2164 S. (MVFF) - Tesoro Refining & Marketing	Santa Maria	Failed to submit the 2014 Annual Report	4/10/2015	206	7/20/2015	\$250
10730	Broadway, 2301 S. (MVFF) - Letters, Ince	Santa Maria	Failed to maintain records as required by permit	3/4/2015	206	7/24/2015	\$250
10705	Chamness Biodegradables, LLC	Carpinteria	Failed to maintain records as required by permit	1/5/2015	206	7/27/2015	\$250
10725	Broadway, 1519 N. (MVFF) - Santa Maria Alliance	Santa Maria	Failed to conduct biannual VRS testing	1/30/2015	206/316	7/31/2015	\$1,500
\$4,000							