

## Notices of Violation Issued September 2011

Nov #	Facility	Location	Source Of Violation	Violation Date	Rule
9845	Innovative Micro Technology	Goleta	Exceeded permitted emission limit	9/8/2011	206
9841	Celite Corporation	Lompoc	Improper operation of emission control devices	9/12/2011	206
9842	Celite Corporation	Lompoc	Improper operation of emission control devices	9/12/2011	206
9843	Celite Corporation	Lompoc	Failed to perform required testing	9/12/2011	206
9844	Celite Corporation	Lompoc	Failed to perform required testing	9/12/2011	206
9636	City of Santa Barbara / El Estero WWTP	Santa Barbara	Failure to obtain a permit for an engine	9/16/2011	201
9783	Santa Maria Airport District	Santa Maria	Failure to obtain a permit for an engine	9/23/2011	201
9784	Rincon Consultants	Buellton	Failure to obtain a permit for a soil cleanup project	9/28/2011	201

## Penalty Settlement Payments Received September 2011

Nov #	Facility	Location	Source Of Violation	Violation Date	Rule	Date Paid	Total Penalty Received
9608	Glad-a-Way Gardens	Santa Maria	Failure to register engines	8/5/2010	1201	9/2/2011	550
9745	E&B Natural Resources / South Cuyama Unit	Cuyama	Tanks with large holes.	1/5/2011	325	9/2/2011	6,000
9423	Venoco / Platform Holly	State Tidelands	Exceeded crane fuel limit on multiple days	10/14/2009	206	9/7/2011	5,000
8750	Mission Ready Mix	Goleta	Failure to use emission control equipment	12/7/2009	206	9/14/2011	500
9756	ExxonMobil Production Co. / Las Flores Canyon	Gaviota	Did not comply with Gas Turbine requirements	2/16/2011	206	9/19/2011	2,500
9759	ExxonMobil Production Co. / Platform Hondo	OCS	Pilot flame not maintained in flare	2/16/2011	359	9/19/2011	10,000
					<b>Total</b>		<b>\$24,550</b>